Vastern Road roundabout

the worst accident location in Reading

Actions are needed

Vastern Road roundabout

Multi-lanes, lots of tarmac and high speeds



Collisions where cyclists injured at Vastern Road

```
• 2018 - ?
```

- 2017 7
- 2016 6
- 2015 5
- 2014 1
- 2013 4
- 2012 1


These figures are horrendously high, being more than on the Oxford Road, or all of Tilehurst, or all of Caversham

JL1 John Lee, 05/01/19

Vastern Road approach to roundabout where most 'failures to give-way' occur



Spiral markings supported, + CADRA mod



Spiral markings supported, but additional measures urgently required

- Better off-carriageway routes for cyclists and pedestrians
 - 1. More direct routes
 - 2. Raised crossings to slow traffic
 - 3. Bigger and more pedestrian (and cycle) refuges
 - 4. Reduce number of traffic lanes where not essential
- Better give-way markings for traffic

Improved give-way markings - European style sharks-teeth Trials by TRL in 2013 CIHT correspondence January 2019





Better off-carriageway routes for cyclists and pedestrians

- 1. More direct routes
- 2. Raised crossings to slow traffic
- 3. Bigger and more pedestrian (and cycle) refuges
- l. Reduce number of traffic lanes where not essential



Policy!?

- Responsibility for Highway Authority to take steps to reduce and prevent collisions
- NICE recommendation in January 2019 to consider pedestrians and cyclists more in traffic schemes, with less priority for motor traffic
- RBC Cycling Strategy seeks to encourage cycling and make it safer
- TMSC should request changes at Vastern Road roundabout until the number of cyclists injured reduces to no more than one a year.