APPENDIX 1 - REQUESTS FOR WAITING RESTRICTIONS 2021A - OFFICER RECOMMENDATIONS

UPDATED: 28/05/21

Ward	Street	Summary of Request	Officer recommendation
Abbey	Jesse Terrace /Castle Hill	Request to extend double yellow lines on Castle Hill by 5- Officers have visited the site and recommend reducing the 10m, west of the junction with Jesse Terrace, in order to existing permit bay by 5m to improve visibility for motorists extension castle Hill existing Jesse Terrace as shown in drawing AR1 Jesse Terrace.	Officers have visited the site and recomme existing permit bay by 5m to improve visible existing lasse Terrace as shown in drawing AR
Ward	Street	Summary of Request	Officer recommendation
Abbey	Chatham Place	To cover the existing 'no waiting at any time' restrictions on this area of non-Highway, but Reading Borough Council will apply to the area of Reading Borough Council bounded in land, with a Traffic Regulation Order that will enable enforcement under the Council's wider parking Civil Enforcement powers. This will bring enforcement in line with the same processes and procedures for the enforcement of waiting restrictions on adopted Highway land across the borough.	To consult on the proposals in plan AB2_Chatl will apply to the area of Reading Borough Coured.

				Caversham					Caversham						Caversham	Ward
			/Hemdean Rise	Hemdean Hill				/Douglas Road	Star Road						Cromwell Road	Street
•	junction.	Rise junction to address visibility issues for drivers caused by parked care in the permit holders have closest to the	additional 5m in all directions on Hemdean Road/Hemdean	Request to extend existing double yellow lines by an			road safety concerns caused by parked cars in this area.	Douglas Road from its junction with Star Road, to address	Request to investigate further waiting restrictions within	issues should be alleviated.	hill. By reducing the length of this bay access/road safety	Access is made difficult by the road layout/camber and	at a property close to the junction with Henley Road.	Cromwell Road by 5m, to address access issues occurring	Request to reduce permit holders bay at north of	Summary of Request
request is removed from the programme.	saturated permit zone. Officers therefore recommend that the	introduced it would also remove a few parking spaces in a highly	have not seen any evidence of issues caused by cars parking	Having visited the site at different times of the day, officers	CA2_Douglas Road.	improve visibility for motorists, as shown in drawing	10m on each side of its junction with Douglas Road in order to	and recommend extending the existing double yellow lines by	Officers witnessed vehicles parking on the east side of Star Road		marking at this location.	available in the permit zone due to an existing access protection	CA1_Cromwell Road. This will not reduce the number of spaces	recommend reducing the parking bay by 5m as shown in drawing	Officers visited the site at different times of the day and	Officer recommendation

waiting restriction review programme.			
scheme then we would recommend that it is removed from the			
programme. Should Shinfield Rd be included in the active travel	cycle lane project which is pending/waiting development.		
parking concerns of residents. Request is in relation to so officers recommend that this request be deferred to the next	parking concerns of residents. Request is in relation to		
Request to investigate waiting restrictions to address The decision regarding the active travel schemes is still pending	Request to investigate waiting restrictions to address	Shinfield Road	Church
Officer recommendation	Summary of Request	Street	Ward

	Katesgrove	Ward
	Ella Garret Close	Street
around the junction with Northumberland Avenue to address safety/access issues caused by parked cars at this junction during school pick up/drop off times.	Request for double yellow lines on areas of public highway	Summary of Request
to junction with Northumberland Avenue as shown in drawing his KA1_Ella Garret Close.	Officers recommend installing double yellow lines around the	Officer recommendation

Kentwood	Kentwood	Ward
Romany Close	Oak Tree Road	Street
Request for double yellow lines on the bend within Romany Close, to address reported access issues for delivery and utility vehicles caused by parked cars around the bend and by the garages.	Request to extend the existing 10m double yellow lines at the junction of Oak tree Road and Carlisle Road on both sides to 20m and add another section of double yellow lines opposite the junction with Carlisle Road to improve visibility.	Summary of Request
any This request went to consultation as part of the 2016A programme and was removed due to objections from residents. However, as we have continued to receive complaints about parking on the bend, officers recommend installing a short length of double yellow lines as shown in drawing KE1_Romany Close.	Request to extend the existing 10m double yellow lines at the junction of Oak tree Road and Carlisle Road on both sides to 20m and add another section of double yellow lines opposite the junction with Carlisle Road to improve visibility. Officers have visited the site and found no evidence of vehicles parking in a manner which affected visibility when manoeuvring around the junction. As there are existing double yellow lines which prevent parking close to the junction, officers recommend that this request to extend the existing 10m double yellow lines around the junction of Oak tree Road and Carlisle Road on both parking in a manner which affected visibility when manoeuvring around the junction. As there are existing double yellow lines to 20m and add another section of double yellow lines around the junction. As there are existing double yellow lines to 20m and add another section of double yellow lines around the junction. As there are existing double yellow lines which parking in a manner which affected visibility when manoeuvring around the junction. As there are existing double yellow lines around the junction with Carlisle Road to improve which parking in a manner which affected visibility when manoeuvring around the junction. As there are existing double yellow lines around the junction of the jun	Officer recommendation

	has been reported to be causing turning/access issues.		
which Crescent.	the public highway, to prevent parking in this area which		
the turning area in Edenham Crescent which forms part of installing double yellow lines as shown in drawing MI1_Edenham	the turning area in Edenham Crescent which forms part of		
Edenham Crescent Request to investigate adding waiting restrictions within In order to keep the turning area clear, officers recommend	Request to investigate adding waiting restrictions within	Edenham Crescent	Minster
Officer recommendation	Summary of Request	Street	Ward

		Norcot	Ward
		Longridge Close	Street
safety/access issues caused by parked cars in this area.	Close and its junction with St Ronans Road, to address road	Request to investigate waiting restrictions within Longridge	Summary of Request
	i road junction as shown in drawing NO1_Longridge Close.	;ridge \mid Officers recommend installing double yellow lines around the	Officer recommendation

ې	ֿפֿר	p ×
Park	Park	Ward Park
Sun Street	Bulmershe Road/Hamilton Road	Crescent Road
Request to install double yellow lines over the entrance to Icarus Court between the two existing permit holder bays.	Request to consider waiting restrictions across the entrance to Maiden Erlegh School.	Request to introduce further waiting restrictions as well as loading bans on areas of existing double yellow lines, to address parking problems/road safety issues outside the Maiden Erlegh School occurring during pick up/drop off times.
As a result of the 2020 waiting restriction review programme, the parking bay at this location is due to be reduced. Officers therefore recommend installing additional double yellow lines as shown in drawing PA2_Sun Street.	Officers note there is an existing loading ban restriction on the highway near the school entrance and officers do not recommend additional restrictions be installed. Councillors have requested a 'school keep clear' restriction, however, due to the minimum length required it will not fit on the highway and would be an unusual placement. Officers recommend that a school keep clear should ideally go over the school entrance and we are currently investigating land ownership at this location. If there is an extent of non-highway land (that is owned by the council) over the entrance, we will seek internal agreement to bring this to the next review programme and develop a proposal for 'school keep clear' restrictions as requested. Please note that if the land outside the entrance is not owned by the Council, we will not be able to take this further.	Officers have visited the site and recommend changing the existing double and single yellow line restrictions to include a 'no loading' restriction during school pick up and drop off periods as shown in drawing PA1_Crescent Road. Officers do not believe that these restrictions would be needed if the road becomes a school street and would recommend removing this from the waiting restriction review programme should this be approved.

Ward	Street	Summary of Request	Officer recommendation
Redlands	Newcastle Road	Request for double yellow lines at eastern end of	Officers have visited the site and do not believe that additional
		Newcastle road, from the junction by the parking area up	double yellow lines would benefit the area. It is likely that the
		the grass area to prevent parking on this side of the road,	majority of cars parking here belong to residents and should any
		which is causing residents difficulties when accessing their	double yellow lines be installed it would reduce the number of
		driveways on the west side of the street.	parking spaces for residents and cause additional issues through
			displacement parking. An area wide permit parking scheme was
			consulted on in 2019, however, residents were not clearly in

Ward	Street	Summary of Request	Officer recommendation
			favour of an area wide scheme. We therefore recommend that this request be removed from the programme.
Redlands	Newcastle Road	Request for Double Yellow Lines by grass verges near flats (139-161) of Newcastle Road to address access/visibility	Officers have visited the site and do not believe that additional double yellow lines would benefit the area. It is likely that the
		issues. Request for marked out bays in layby area.	majority of cars parking here belong to residents and should any double yellow lines be installed it would reduce the number of
			parking spaces for residents and cause additional issues through
			constituted on in 2010 however residents were not clearly in
			רטושמונבט טוו ווו בטוד, ווטאפייפו, ובשותבוונט איבו ב ווטר כנבמונץ ווו
			favour of an area wide scheme. We therefore recommend that
			this request be removed from the programme.
Redlands	Redlands Road	The Traffic Regulation Order created for the Redlands Road	Following completion of the works at this location, officers can
		area 20mph enhancements CIL funded scheme needs to be	confirm that the parking bay does not require any amendment,
		amended to show the correct measurements for the parking	so we recommend that this be removed from the programme.
		bay between 70 and 64 Redlands Road, as the result of the	
		new build out.	

Southcote	Southcote	Ward
Southcote Lane	Liebenrood Road	Street
Request for double yellow on Southcote Lane close to the junction with Monks Road, to address visibility/access issues at this junction caused by parked cars on both sides of Southcote Lane.	Request for double yellow lines in Liebenrood Road opposite the junction of Penroath Road to improve access to vehicles par Penroath Avenue, especially when events are held at along Lieben Prospect Park due to the vehicles parking on Liebenrood and can end Road and over-spilling into Penroath Avenue. Request to review the current waiting restrictions within Penroath We therefore Avenue to prevent residents and their visitors not being programme, able to park due to over-spill from events at prospect park and English Martyrs Church.	Summary of Request
Officers recommend installing a short section of double yellow lines as shown in drawing SO1_Southcote Lane.	Officers have visited the site and have not seen any evidence of vehicles parking dangerously at this location. Vehicles parking along Liebenrood Road can also act as a traffic calming feature and can encourage vehicles to slow down. There are existing double yellow lines around the junction with Penroath Avenue. We therefore recommend removing this request from the programme.	Officer recommendation

driveways, they can apply for an access protection marking. We			
residents have any issues with vehicles parking over their			
of vehicles parking obstructively at this location. Should	commuter parking in this location.		
to stop Officers have visited the site and have not found any evidence	Request for double yellow lines in front 18 and 45 to stop	Wrenfield Drive	Thames
Officer recommendation	Summary of Request	Street	Ward

Tilehurst	Tilehurst	Ward		Ward
Fern Glen	Bevan Close	Street		Street
at school drop off/collection times. At school drop off/collection times. Request for double yellow lines at the junction of Fern Glen and Pierces Hill to address visibility issues/road safety concerns in this area caused by parked cars close to the junction and on grass verge areas.	Request to investigate waiting restrictions within Bevan Officers recommend installing so Close and its junction with Conwy Close to address shown in drawing TI1_Bevan Close.	Summary of Request		Summary of Request
n Glen Officers recommend installing double yellow lines around the safety junction as shown in drawing TI2_Fern Glen.	Officers recommend installing some double yellow lines as shown in drawing TI1_Bevan Close.	Officer recommendation	therefore recommend removing this request from the programme.	Officer recommendation

Ward	Street Kingshridge Road	Summary of Request Request for double vellow lines to be installed to prevent
Whitley	Kingsbridge Road	Request for double yellow lines to be installed to prevent Officers visited the site and did not see any vehicles parking obstructive parking around the width restriction on the obstructively and therefore recommended to remove the
		bend within Kingsbridge road.